

Electrical Machine

By Ankit Goyal Sir


GATE EE 2018 AIR 1



www.kreatryx.com

INDEX

1. Introduction.....	2
2. Transformer.....	56
3. Electromechanical Energy Conversion.....	294
4. D.C Machine.....	315
5. Synchronous Machine.....	463
6. Induction Machine.....	695
7. Special Machine.....	850



USE CODE

ANKITKR10

TO GET

MAX DISCOUNT ON

plus
Subscription

Chapter 1: Basic Introduction

1. Electrical material
 - a. Conducting material
 - b. Magnetic material
 - i. Domain theory
 - ii. Magnetic material type
 - c. Insulating material
2. Basic laws of electromagnetism
 - a. Biot – Savart's law
 - b. Ampere's law
3. Electromagnetic induction
 - a. Faraday's law
 - b. Lenz's law
4. Type of induced E.M.F
 - a. Statically induced E.M.F
 - b. Dynamically induced E.M.F
5. Force produced by mag field
 - a. Force on Moving charge
 - b. Force on current carrying charge
6. Motional E.M.F

INTRODUCTION

→ Electrical Material

- i) Conducting Material
- ii) Magnetic Material
- iii) Insulating Material

* Electrically Conducting Material

These materials carry current in elect. machine.

- i) Highly Conducting Material
- ii) Highly Resistive Material

Cu, Al, Au, Ag ⇒ HCM
Alloys ⇒ HRM

- ⇒ Heating element and highly resistive material use alloy. These, steel wire.
- ⇒ Alloy and Alloy (Fe-Cr-Ni) used.
- ⇒ Alloy of temperature co-efficient is low.
- ⇒ Resistance Alloy of wire used.

Property of Highly Conducting Material

- ⇒ Highest possible conductivity.
- ⇒ less temp co-efficient of Resistance.
- ⇒ Adequate of Mechanical strength and absence of brittleness.
- ⇒ Rollability and drawability should good.

$\sigma =$ Condu
ctivity

$$\sigma_{Au} > \sigma_{Ag} > \sigma_{Cu} > \sigma_{Al}$$

$$\alpha_{Cu} = 0.00393 / ^\circ C$$

Similar are conductive
[Au wire & Ag wire?]

- \Rightarrow Good weldability & solderability to ensure low resistance of joints
- \Rightarrow Addict Resistant to corrosion.

<1.> Copper

- \Rightarrow Machine winding wire.
- \Rightarrow Copper is resistant to oxidation and corrosion.
- \Rightarrow Hard drawn copper wires are used in electrical machine because their mechanical strength is high.

$$\alpha_{Cu} = 0.00393 / ^\circ C$$

↑
Temp co-efficient of copper

<2.> Aluminium

- \Rightarrow Since copper is getting depleted Alumi. is the next best choice for conducting material.
- \Rightarrow As it is abundantly available
- \Rightarrow Aluminium can not be drawn into thin wire but it can be use for form thin plates

For same resistance The cross section of Al is more than Cu

Parameters	Cu	Al
Cost	1	0.49
Cross Section	1	1.62
Diameter	1	1.27
Volume	1	2.04
Weight	1	0.49
Strength	1	0.64

we know, $\sigma_{Cu} > \sigma_{Al}$

$\sigma = P/A$

$$R = P/A = \frac{l}{\sigma A}$$

$$(P = I/\sigma)$$

$$R_{Cu} = R_{Al}$$

$$\frac{l}{(A\sigma)_{Cu}} = \frac{l}{(A\sigma)_{Al}}$$

$$(A)_{Al} = \frac{(A)_{Cu} (\sigma)_{Cu}}{(\sigma)_{Al}}$$

as the $\sigma_{Al} < \sigma_{Cu}$

we get $(A)_{Al} > A_{Cu}$

Interview

- Q Why cross sectional area is more than copper
- ⇒ $\rho_{Al} > \rho_{Cu}$, cu has less resistivity area required is less Al being conductive eq.
- ⇒ For aluminium wire the size of slot require is higher as compare to cu.
- ⇒ For induction motor above 100kW Al can be used for cage rotor.
- ⇒ Al can be used to form foil type low voltage winding in transformer.
- ⇒ Al can be used to construct the tank of transformer to reduce stray losses.
- ⇒ Al is easily gets oxidised to form Al_2O_3 layer which prevent further oxidation.

<3> Electrical Carbon

- ⇒ This material is made up of graphite or other form of carbon.
- ⇒ Conductivity of carbon is less than of cu & Al. but its surface is smoother so it is used to make brushes in an electrical machines.

Graphite has -ve temp co-efficient.

—/—/—

⇒ Carbon brushes are graphited and heat treated to increase conductivity and increase smoothness.

⇒ Graphite has -ve temp co-efficient


So $T \uparrow \Rightarrow R \downarrow$

So $V_{BD} = IR \Rightarrow$ Brush drop is constant.

Cu \Rightarrow Winding α

Al \Rightarrow Trans. Tank α

Carbon \Rightarrow Brush α



Magnetic Materials

* ————— *

⇒ The material which allows flow of magnetic field through them are called as magnetic material.


i) Diamagnetic Material.

ii) Paramagnetic Material.


iii) Ferromagnetic Material.



* <u>Di</u> Diamagnetic *



no dipoles in absence of magnetic field.



⇒ In diamagnetic material there is no magnetism in absence of external field.

⇒ When magnetic field is applied dipoles are induced and they orient in direction opposite to external mag. field.

magnetization (M)

↓
ability of dipoles to align when mag. field is applied.

$$\vec{M} = \chi_m \vec{H}$$

↓
~~SIP~~ P
Pronounce as
SIP

(\vec{H} = ext. mag field)
(χ_m = mag. susceptibility)

What is Susceptibility

What is Permeability

Susceptibility shows that for some value of magnetic field how ~~are~~ strong material get magnetize.

Susceptibility is a measure of material to get magnetize when external mag. field is applied.

in diamagnetic material

\vec{M} & \vec{H} are opposite to -

$$\boxed{\text{So } \chi_m < 0}$$

$$\mu = \mu_0 \mu_r$$

μ_0 = Permeability of free space / vacuum
 $= 4\pi \times 10^{-7} \text{ H/m}$

μ_r = relative permeability.

$\mu_r = 1 + \chi_m < 1$ in diamagnetic.

So $\mu < \mu_0$


\Rightarrow Permeability of material is related to ability of material to allow magnetic field lines to pass through it.

\Rightarrow Magnetic flux density (B) represents the closeness of of magnetic field line to each other in unit surface area.

$$\vec{B} = \mu \vec{H}$$

$$\mu < \mu_0$$

$$\therefore \vec{B}_{\text{air}} > \vec{B}_{\text{diamagnetic}}$$



diamagnetic material,
air field line diverge away from each other.

⇒ In a diamagnetic material the magnetic field line diverge away from each other.


ex: Cu, Silicon, Germanium, Gold
Diamond.

सिद्धांत शब्द सबल spin of unpaired electron.




ii Paramagnetic

⇒ In paramagnetic material the magnetic dipoles already exist due to spin of unpaired electron in an atom



→ H = 0



→ H

⇒ In paramagnetic material magnetic dipoles are randomly oriented but when mag. field is applied such dipole align parallel to external mag. field.

$$\vec{M} = \chi_m \vec{H}$$

\vec{M} Parallel to \vec{H}

So $\chi_m > 0$

$$\mu_r = 1 + \chi_m > 1$$

$$\mu > \mu_0$$

$$\vec{B}_{ind} < \vec{B}_{para}$$